MARYLAND DEPARTMENT OF THE ENVIRONMENT

LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO. 821682

MDE TRACKING NO.	MDE PROPERTY NO. (Include county code prefix.)	OWNER NAME
345704	0327 23 4429 D 014	Kinder Narcissus LLC

Street Address	Unit No.	City	Zip Code	County	Property Construction Date
5803 Narcissus Ave	2	Baltimore	21215	Balt City	0000

The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only **ONE** category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a $10 per unit processing fee for each certificate. To be paid to: P.O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection. Inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors **must** mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794.

INSPECTION CATEGORIES

☐ 1. Lead Free

Methods

☐ **A.** One Time Only *(Interior & Exterior)*

OR

☐ **B.** Limited *(Interior Lead Free Only)*
Passing Re-inspection required no later than: ___/___/___

___ Number of Pre-1950 Lead Free Units
___ Number of Post-1949 Lead Free Units

☑ 2. Full Risk Reduction

Methods

☑ **A.** Dust Inspection

OR

☐ **D.** Dust Inspection with Exterior Waiver

Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04 / 30 /___ unless otherwise noted in local code.

OR

☐ **E.** Dust Inspection with Lead Free Exterior

☐ 3. Modified Risk Reduction

Methods

☐ **B.** Visual Inspection **and** Dust Inspection

OR

☐ **C.** Visual Inspection **and** Dust Inspection with Exterior Waiver

Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04/ 30 /___ unless otherwise noted in local code.

OR

☐ **D.** Visual Inspection **and** Dust Inspection with Lead Free Exterior

☐ 5. Lead Safe

Methods

☐ **A.** Dust Inspection

OR

☐ **B.** Dust Inspection **and** Visual Inspection

OR

☐ **C.** Dust Inspection with Lead Free Exterior

OR

☐ **D.** Dust Inspection **and** Visual Inspection with Lead Free Exterior

AND

Verification that windows are lead free or have been treated so friction surfaces are lead free.

☑ **PASSED** Based on the findings of the attached inspection report(s), I certify that the **property/unit** meets the certification criteria at this time. *(circle property or unit)*

☐ **FAILED** Based on the findings of the attached inspection report(s), the **property/unit** fails to meet certification criteria at this time. *(circle property or unit)*

I certify that I inspected the above listed **property/unit** on 10/27/17 at 1 :30 **a.m./p.m.** under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.

Inspector's Name	Inspector's Signature	Accreditation No.	Accreditation Exp. Date	Inspection Contractor Name	Accreditation No.	Accreditation Exp. Date
Zvi Pollack	Z. Pollack	13816	11-29-2018	Quality Inspections	9830	11-29-2018

Form Number: MDE 330, *Revised: 04/2017* ***(copy distribution: original to owner; yellow to MDE; pink to tenant; goldenrod to inspection contractor)***