

MARYLAND DEPARTMENT OF THE ENVIRONMENT 882160

LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO.

0345704

MDE TRACKING NO.

5801 Narcissus Ave

0327234429D014

MDE PROPERTY NO. (Include county code prefix.)

3 Baltimore

Kinder Narcissus LLC

OWNER NAME

21215 Balt. City 0000

Street Address

Unit No.

City

Zip Code

County

Property Construction Date

The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a \$10 per unit processing fee for each certificate. To be paid to: P.O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection. Inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors must mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794.

INSPECTION CATEGORIES

☐ 1. Lead Free	☒ 2. Full Risk Reduction	☐ 3. Modified Risk Reduction	☐ 5. Lead Safe
Methods ☐ A. One Time Only (Interior & Exterior) OR ☐ B. Limited (Interior Lead Free Only) Passing Re-inspection required no later than: ____ / ____ / ____ Number of Pre-1950 Lead Free Units ____ Number of Post-1949 Lead Free Units ____	Methods ☒ A. Dust Inspection OR ☐ D. Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04 / 30 / ____ unless otherwise noted in local code. OR ☐ E. Dust Inspection with Lead Free Exterior	Methods ☐ B. Visual Inspection and Dust Inspection OR ☐ C. Visual Inspection and Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04 / 30 / ____ unless otherwise noted in local code. OR ☐ D. Visual Inspection and Dust Inspection with Lead Free Exterior	Methods ☐ A. Dust Inspection OR ☐ B. Dust Inspection and Visual Inspection OR ☐ C. Dust Inspection with Lead Free Exterior OR ☐ D. Dust Inspection and Visual Inspection with Lead Free Exterior AND Verification that windows are lead free or have been treated so friction surfaces are lead free.

☒ **PASSED** Based on the findings of the attached inspection report(s), I certify that the property/unit meets the certification criteria at this time. (circle property or unit)

☐ **FAILED** Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit)

I certify that I inspected the above listed property/unit on 10/7/19 at 2:00 a.m.(p.m.) under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.

Inspector's Name: Zvi Pollack 3. Mr. 13816 11-29-2020 Quality Inspections 9830 11-29-2020

Inspector's Signature: _____ Accreditation No. _____ Inspection Contractor Name: _____ Accreditation No. _____ Accreditation Exp. Date: _____

Form Number: MDE 330, Revised: 04/2017 (copy distribution: original to owner; yellow to MDE; pink to tenant; goldenrod to inspection contractor)