

MARYLAND DEPARTMENT OF THE ENVIRONMENT
 LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO. **854440**

MDE TRACKING NO. 035134Z
 MDE PROPERTY NO. (include county code prefix.) 04-14-1423 001475
 Street Address 4209 FULBERTON AVE Unit No. 1ST FLE City LAUREL Zip Code 21204 County Baltimore Property Construction Date 1922
 Inspector's Name Sherry Coley Inspector's Signature [Signature] Accreditation No. 16115 Accreditation Exp. Date 11-1-20 Inspection Contractor Name ANN QUALITY HOME TRNG Accreditation No. 847 Accreditation Exp. Date 3-15-19

The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a \$10 per unit processing fee for each certificate. To be paid to: P. O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection. Inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors must mail inspection certificates and the supporting documentation for inspection certificates to: P. O. Box 943, Jessup, MD 20794.

<input type="checkbox"/> 1. Lead Free Methods <input type="checkbox"/> A. One Time Only (Interior & Exterior) OR <input type="checkbox"/> B. Limited (Interior Lead Free Only) Passing Re-inspection required no later than: ___/___/___ Number of Pre-1950 Lead Free Units Number of Post-1949 Lead Free Units	<input checked="" type="checkbox"/> 2. Full Risk Reduction Methods <input checked="" type="checkbox"/> A. Dust Inspection OR <input type="checkbox"/> D. Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04/30/___ unless otherwise noted in local code.	<input type="checkbox"/> 3. Modified Risk Reduction Methods <input type="checkbox"/> B. Visual Inspection and Dust Inspection OR <input type="checkbox"/> C. Visual Inspection and Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04/30/___ unless otherwise noted in local code.	<input type="checkbox"/> 5. Lead Safe Methods <input type="checkbox"/> A. Dust Inspection OR <input type="checkbox"/> B. Dust Inspection and Visual Inspection OR <input type="checkbox"/> C. Dust Inspection with Lead Free Exterior OR <input type="checkbox"/> D. Dust Inspection and Visual Inspection with Lead Free Exterior AND Verification that windows are lead free or have been treated so friction surfaces are lead free.
--	--	--	--

PASSED Based on the findings of the attached inspection report(s), I certify that the property/unit meets the certification criteria at this time. (circle property or unit)
 FAILED Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit)
 I certify that I inspected the above listed property/unit on 2/13/19 at 7:00 a.m./p.m. under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.